

2015

REHABILITATION of Existing Sewer Drain Tanks Culvert @ Caerphilly County Borough Council

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
(ID)876mm x 1.20m / Wall 12.5mm	17 Meters	15	1	ONE PIECE CIRCULAR	iGroup Technologies UNITED KINGDOM (2015)



REHABILITATION of Taikoo Outfall Pipe @ City Plaza, Taikoo

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
Straight Panels (ID)850mm x 0.37m / Wall 18mm	16.12 Meters	44	1	ONE PIECE CIRCULAR	INNOPIPE ENGINEERING COMPANY LIMITED HONG KONG (2015)
Curve Panels (ID) 850mm x 0.268m / Wall 18mm	1.876 Meters	7	1		



REHABILITATION of Existing Cp5 Culvert Structure @ Mouldsworth

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
1230mm x 1650mm X 2.4m / Wall 25mm	16.12 Meters	42 Meters	18	ONE PIECE CIRCULAR	iGroup Technologies UNITED KINGDOM (2015)



REHABILITATION of Existing Sewer Invert @ Demetskaai Te Anderlecht

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
650mm x 730mm X 2.2m / Wall 12mm	45 Meters	21	1	ONE PIECE CIRCULAR	RENOTEC BELGIUM (2015)



100 Avenue to 99 Ave Deep Sewer Tunnel REHABILITATION @ Edmonton

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
1578mm x 908mm X 2.4m / Wall 36mm	200 Meters	83	4	ONE PIECE BOX WITH ARCH TOP SLIPLINE JOINT	ASC TRENCHLESS TECHNOLOGIES INC. CANADA (2015)




COS REHABILITATION of Central Outfall Sewer Slauson Ave To Vernon Ave @ City Of Los Angeles

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
Straight Panels 1702mm x 1245mm x 2.44m / Wall 25mm	5270 + Feet	659 +	10	ONE PIECE OVOID WITH INLINE JOINT	MLADEN BUNTICH CONST. CO., INC. USA (2015)



REHABILITATION of Existing Sewer @ Kwei Chow Street Hong Kong

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
Ø1450mm(ID) x (L) 1.50mm/WALL 26mm	70 Meters	48	3	ONE PIECE CIRCULAR	WORLD DIAMOND ENGINEERING LIMITED HONG KONG (2015)



REHABILITATION of Existing Box Culvert @Warrenville Road, Shaker Heights, Ohio

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
4' -0.34" x 9' -0.58" x 7.55'/WALL 49mm	116 Feet	116 116	1-Invert 1-Crown	TWO PIECE BOX CULVERT	TRIAD ENGINEERING & CONTRACTING U.S.A (2015)



REHABILITATION of Egg Shaped Sewer @ New Wapping Street Dublin, Ireland

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
810mm x 490mm x 1.20m/ Wall 10mm	48 Meters	40	2	ONE PIECE EGG	GMC UTILITIES GROUP LIMITED IRELAND (2015)



REHABILITATION of Egg Shaped Sewer @ Townsend Street Dublin, Ireland

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
795mm x 495mm x 1.20m/Wall 10mm	69.60 Meters	47	1	ONE PIECE EGG	GMC UTILITIES GROUP LIMITED IRELAND (2015)




REHABILITATION of Egg Shaped Sewer @ Townsend Street Dublin, Ireland

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
1670mm x 792mm x 1.20m/Wall 19mm	85.20 Meters	71	3 - STRAIGHT 1 - TRANSITION	ONE PIECE EGG	GMC UTILITIES GROUP LIMITED IRELAND (2015)



REHABILITATION of Bath Slough Arch Culvert @ Richmond Canada

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
3170mm x 1273mm x 1.95m/WALL 55mm	9.75 Meters	5	1 - INVERT 1 - CROWN	TWO PIECE ARCH CULVERT	P.W. TRENCHLESS CONSTRUCTION INC. CANADA (2015)



REHABILITATION of Existing Egg Shaped Sewer @ Selkirk Street Winnipeg, Canada

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
1750mm x 1390mm x 2.3m/WALL 25mm	131.5 Meters	57	3	ONE PIECE EGG	SADE CANADA INC. CANADA (2015)



REHABILITATION of Existing Egg Shaped Sewer @ Mission Street Winnipeg, Canada

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
2642mm x 1642mm x 2.3m/WALL 34mm	49.97 Meters	21	2	TWO PIECE EGG	SADE CANADA INC. CANADA (2015)



REHABILITATION of Existing Sewer @ Beccles, Uk

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
1210mm/WALL 25.9mm	30 Meters	21	2 - Wooden Mould	CIRCULAR	iGroup Technologies UNITED KINGDOM (2015)
1115mm/WALL 25.9mm	3 Meters		1- Wooden Mould		
1210x1115mm/WALL 25.9mm	1 Meter		1- Transition		



NOS REHABILITATION Unit 2 Western to Vernon @ City of Los Angeles

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
Straight Panels 1651mm x 1889mm x 2.44m / Wall 38mm	5,812.4 Feet	717	7	ONE PIECE OVOID WITH INLINE JOINT	SPINIELLO COMPANIES USA (2014-2015)
Curve/Bend Panels 1651mm x 1889mm / Wall 38mm	378.22 Feet	148	5		



NOS REHABILITATION Unit 5 San Pedro To Hooper @ City Of Los Angeles

DIMENSIONS	LENGTH	NO. OF PANELS PRODUCED	NO. OF MOULDS MADE	PROFILE	CONTRACTOR / LOCATION / YEAR
Straight Panels 1499mm x 1706mm x 2.44m / Wall 38mm	4,037 Feet	511	6	ONE PIECE OVOID WITH INLINE JOINT	SPINIELLO COMPANIES USA (2014-2015)
Curve/Bend Panels 1499mm x 1706mm / Wall 38mm	4,037 Feet	117	5		

